

VISIT REPORT Maintenance & repair.

Ship No.: KV HEIMDAL	Shipyard: VARD Langsten	Report No.: 2	
Owner: Kystvakten	Location: Tomrefjord	Page 1 of 1	
Area: TK 10 WB /12 WB STB /12 WB PS	Contractor: North side	Date: 25.05.22	
Stage at time of visit: DFT inspection		Application: Airless spray/Brush	
Product Name:	Coat No.:	Colour	D.F.T.
Jotacote UNI	1	ALRT	160 microns
Jotacote UNI	2	GREY	160 microns
PRESENT:			
NAME:		COMPANY:	
Bjarte Bakken		VARD Langsten	
1.man		North side A/S	
None		Kystvakten	
Mareno Ernes		Jotun A/S	
Comments:			
<p>DFT inspection preformed upon request from Vard Langsten 25.05.22 with following results on TK 10 WB/ 12 WB SB/ TK 12 PS:</p> <p>TK 10 WB 111 readings mean average=614,7microns. TK 12 WB PS 51 readings mean average=484,0 microns. TK 12 WB SB 43 readings mean average=581,4 microns</p> <p>DFT on all tanks mentioned above are according to specification or over expect from some minor T/U required:</p> <ul style="list-style-type: none"> - T/U after mounting of new zinc anodes, some few scallops and shadows sides on welding seams marked up for T/U during inspection. 			



Tk 10 WB



TK 12 PS



TK 12 SB